K30 Panel Partitions – KK Duraspan

TYPE OF HOARDING

112   RE-LOCATABLE HOARDING SYSTEM: FLOOR TO CEILING 500
  • Hoarding type: Temporary
  • Hoarding System:
   - Supplier: **Hoarding Warehouse Limited**
        10-14 Ward Street, Bradford, West Yorkshire, BD7 3PR
        Telephone: 0845 058 4999 Email: info@hoardingwarehouse.co.uk
        www.hoardingwarehouse.co.uk

   -     Product reference: **Floor to Ceiling 500**
   -     Panel Type: Extruded PVC Panel Partition
   -     Panel Thickness: 35mm [50mm & 100mm on request to stabilise heights up to 5.5m)
   -     Panel Widths: 500mm
   -     Panel Material Source: Recycled
   -     Colour: White
   -     Fixings: Consult with Manufacturer, identifying hoarding height
  • Partition height: As drawings 2500mm | 3000mm | 4000mm | bespoke on request
  • Partition abutments:
   -     Top: Top Trim 35mm
        Bottom: Trim 35mm
        Deflection allowance: To Structural Engineer's Recommendation.
   -     Floor: 35mm Base Track Channel.
  • Partition joints:
   -     Vertical: Interlocking Panels
   -     Horizontal: 35mm H-Divider (if needed)
   -     90 Degree Corners: 50mm Corner Flashing
   -     Non-90 Degree Corners: 50mm x 50mm Flexi Angle
  • Accessories: Flexi Angle at Window Reveals / Openings.

INSTALLATION

410   WORKMANSHIP GENERALLY
  • Setting out: Plumb, true to line and level, and free from bowing, undulations
    and other planar distortions.
  • Joints: Align accurately with no lipping.
  • Stability: Fixes securely to horizontal scaffold bars at rear using special clips
  • Moisture and thermal movement of framing/ panels: Make adequate allowance.

425   INSTALLING RE-LOCATABLE HOARDINGS
  • Site dimensions: Check before installation. Give notice of discrepancies.

- Perimeter abutments: Accommodate deviations whilst maintaining partition system performance. Form make up/ closer pieces accurately around projections and features.
- Customisation: Do not cut or otherwise alter framing/ panels on site, except where shown on drawings.
- Intermediate joints in exposed frame members and trims: Keep to a minimum.